


PART- 1

PROFORMA FOR THE SAFETY OF SCHOOL BUILDING

(To be filled by the Head of School/ Institute)

1. Name of the School : St. Soldier Divine Public School
2. Location : Mithu Basti
3. Plot Area : 4.5 Acres
4. Plinth Area : 40598 – Sq. Ft.
5. Number of Storey's : 3 Storey's
6. Year of Construction of Building : 1996
7. If the building has been constructed under the supervision of the qualified Engineer, Yes
the following details may be given.
 - a) Name of the Engineer with qualification : ER. RAJ KUMAR BE. CIVIL
 - b) Address of Engineer : 301, Raj Park Jalandhar
 - c) Details of Structural drawings used in the construction : Rajinder Arc. B.A., B.E.
 - d) Name & address of Architect with qualification. Gurbanta Singh Building
8. Whether the building has been constructed for the purpose of
 - a) School YES/NO
 - b) Residential Purpose and converted for use as a School YES/NO
9. Materials used for roofs
 - a) R.C.C. Slabs/R.B.C. Slabs YES/NO
 - b) R.S. Joist & Battens YES/NO
 - c) Wooden joists & Battens YES/NO
10. Materials used for walls
 - a) Mud Mortar YES/NO
 - b) Cement Mortar YES/NO
 - c) Plaster
 - i) Lime mortar YES/NO
 - ii) Cement mortar YES/NO
11. Flooring :-
 - a) Conglomerate YES/NO
 - b) Terrazzo YES/NO
 - c) Brick Paving YES/NO
12. A detailed drawing indicating dimensions of the rooms
Along with size and location of doors and windows YES/NO
13. Whether fire safety certificate obtained YES/NO
14. It is also certified that there is no any court case of stay is
pending regarding this building in any Hon'ble court YES/NO


Principal
St. Soldier Divine Public School
Master Gurbanta Singh Marg
Kpt. Road, Jalandhar

PART-II
(TO BE FILLED BY THE S.D.E. OF P.W.D B&R DEPARTMENT)


Name of School: St. Soldier Divine Public School Basti Mithu Jalandhar

- ✓
- a) This office assistant Engineer/Junior Engineer visited the above mentioned school on dated 4.5.2026 and have visually inspected it from all angles of safety and find it fit for normal use as School building.
- b) In case any addition/ alteration or expansion and modifications to this buildings is to be carried out, the same be carried out under the supervision of a qualified Engineer and this certificate may be re-obtained after the completion from the undersigned.
- c) In case the building is affected by flood, or if there is settlement of walls/ foundations or sagging of roofs etc. immediate inspection of the undersigned by arranged to check the stability and safety of the building.
- d) This building is found visually safe hence it is expected that it can be safely occupied for normal use up to (indicate up to which it can be used) **2026-2027 (up to 31-03-2027)**

upto 31.3.2027 (2026-2027). The School Building is
VISIBLY SAFE & can be used upto 31.3.2027
(2026-2027).

Ref No 71

Dated 5/5/2026


Sub Divisional Engineer
Provincial Sub Divn. No.1
PWD B&R Br. Jalandhar Cantt